Hot Spot 02:			(by Item)		
Site ID#:	FCD-SF02	Top 4 Types of Trash Removed:	Percentage:	Volume of Trash Removed During Cleanup:	
Lat:	N 37.97201	GLASS	49.3%	Size of trash bag (in gallons): 30	
Long:	W 122.04800	PLASTIC	17.2%	Total # of bags: 19 (and 604 Pounds Non-Bagged Debris)	
Watershed:	Pine Creek/Gallindo Creek	METAL	12.3%	OR	
Waterbody:	Pine Creek	MISCELLANEOUS	7.2%	Total Cubic Yards:	
Ownership:	FCD	Potential Trash Pathways/Sources:		Total Weight: 968 lbs.	
Jurisdiction(s):	Concord	Illegal Dumping			
Map: see separa	ate aerial photo on CD	Trash Accumulation			
		Litter			
		Photodocumentation (Before Cleanup)		Photodocumentation (After Cleanup)	
		FCD02_100407_AB_MID_1		FCD02_100407_AB_MID_2	
		FCD02_100407_BC_MID_1		FCD02_100407_BC_MID_2	<u></u>
		FCD02_100407_CD_MID_1		FCD02_100407_CD_MID_2	
		FCD02_100407_DE_MID_1	<u> </u>	FCD02_100407_DE_MID_2	
		FCD02_100407_EF_MID_1	<u> </u>	FCD02_100407_EF_MID_2	
		FCD02_100407_FG_MID_1	(by Item)	FCD02_100407_FG_MID_2	(by Item)
		Item:	Percentage:	Item:	Percentage
		Plastic Bags	1.4	Construction Debris	1.8
		Convenience/Fast Food Items	3.4	Toxic Substances	0.7
		Bottles (Plastic or Glass)	2.7	Large Items	1.9
		Aluminum Cans	1.6	Miscellaneous Items	5.7
		Styrofoam (pieces or pellets)	0.1	Fabric and Cloth	2.4
		Other Plastic Products	12.0	Yard Waste (inc. trees)	0.0
		Paper and Cardboard	5.6	Leaf Litter Piles	0.0
		Cigarette Butts	1.5	Glass Pieces	47.2
		Spray Paint Cans	0.1	Golf or Tennis Balls	0.1
		Metal products	10.7	Other	0.9
		Biohazards	0.2		